New Bedford Water Works. No.1485

RETURN OF SERVICE PIPE.

Put in by Service Pipe I inches diamet Cost to be paid by the City.	er. Inly 247		1873
Cost to be paid by the City.			
	Cost to be paid by the Proprietor.		
lineal feet earth exc. at cts. lineal feet rock exc. at cts. lineal feet lead pipe at cts. lineal feet iron pipe at cts.	5.3 lineal feet earth excavated at 23cts. lineal feet rock excavated at cts. lineal feet lead pipe at 35 cts. lineal feet iron pipe at cts.	1 2	27
	Amount charged Proprietor,	3	97

Ger B Wheeler superintendent.

SERVICE PIPE, No. 1483
Laid for
Lydia W. Barker- 105 Marfild Street.
105 Mas file Street.
1873
Expense to the City,
Expense to the Proprietor,
Total,

Water Registrar's Office,

New Bedford, 7/22 1873

To the Sup't of the N. B. Water Works:

Please put in a Service at the estate named on the back of this Order and return the expense thereof, &c., to my Office.

PAH cul and for water Registrar.