Barn.

5/8" connec. NEW BEDFORD WATER WORKS.

Ser. #7902.

to be made by taker.

SERVICE PIPE RETURN.

Metered by Ser. #7902.

No. 15082 C

Now supplied by Ser. #6957, which is NOT to be removed except inside street line.

No. Rear 213 Brownell	
The expense for valor and materials to be paid	
by the applicant is as follows:	
lineal feet of earth excavated at cents per foot, lineal feet of rock excavated at cents per foot, lineal feet of inch lead pipe at cents per foot, lineal feet of inch iron pipe at cents per foot, lineal feet of inch tin lined pipe at cents per foot, Connection made by owner March 27-1913 using 78 in h lead feifee	
Proportion of other expenses for putting services into premises Amount	

Office of Superintendent,

R. B. P. Boggeshall Superintendent.

WATER REGISTRAR'S OFFICE.

Mar. 4, 1913. 191

To the Superintendent of the New Bedford Water Works:

Please put in a Service upon the premises described above, and make return of the expense of the same to this office.

6. Baylies Water Registrar. per 14. T.

150820 Rear 213 Brownell H. J. Fredette