

Garage.

✓ Connec. of  
5/8" ser.

## NEW BEDFORD WATER WORKS.

#5017 at 167 Allen,  
and metered with same.

## SERVICE PIPE RETURN.

Lay in trench with drain.

No. 16093For Walter S. Macaulay,No. Rear N. side Allen (#167) E. of Cottage Street.

The expense for labor and materials to be paid  
by the applicant is as follows:

-----lineal feet of earth excavated at      cents per foot,

-----lineal feet of rock excavated at      cents per foot,

✓ 64 lineal feet of 5/8 inch H lead pipe at 21 cents per foot,      13 44-

-----lineal feet of      inch      iron pipe at      cents per foot,

-----lineal feet of      inch tin lined pipe at      cents per foot,

1 lb. solder<sup>30</sup>; labor 1.44; casting .25      1 99-Trench dug by Tabor.

Proportion of other expenses for putting services into premises

Amount

\$

0 00  
15 43 (R)

Office of Superintendent,

July 12th, 1915,  
R. B. P. Boyershall Superintendent.

## WATER REGISTRAR'S OFFICE.

March 2, 1915. 191

To the Superintendent of the New Bedford Water Works:

Please put in a Service upon the Premises described above, and make  
return of the expense of the same to this office.

E. Baylies Water Registrar.  
per W. T.17  
13



16093C

R. 167 Allen, N. side,  
E. of Cottage.

Walter S. Macaulay