

Lunch Cart.

Connec. of
5/8" ser. **NEW BEDFORD WATER WORKS.**
#13981 at 185 So. Second
and to be metered with same.

SERVICE PIPE RETURN.

Taker will dig trench
and advise when ready.

No. 16711For Joseph J. Dillon,No. W. side So. Second, S. of Cannon Street

*The expense for labor and materials to be paid
by the applicant is as follows:*

.....lineal feet of earth excavated at	cents per foot,
.....lineal feet of rock excavated at	cents per foot,
.....lineal feet of inch lead pipe at	cents per foot,
.....lineal feet of inch iron pipe at	cents per foot,
.....lineal feet of inch tin lined pipe at	cents per foot,

*Connection of Appl's 13981 made by
Owner, using 12 ft. 7/8" - 2 1/2 lbs. lead
pipe*

Proportion of other expenses for putting services into premises . . .

Amount \$

Office of Superintendent,

June 30 - 1916.
R. B. P. Boyershall Superintendent.

WATER REGISTRAR'S OFFICE.June 26, 1916. 191

To the Superintendent of the New Bedford Water Works:

Please put in a Service upon the Premises described above, and make
return of the expense of the same to this office.

E. Baylies Water Registrar.
per W. D.

1121
141

16711c

St. Second W. side,
N. of Cannon
Joseph J. Hillen