

5/8" ser.

NEW BEDFORD WATER WORKS.

Garage not to be connected.

No. 16996

For William R. Modesto,

No. W. side Crapo, N. of Scott Street

15-14

138-

246 -

200

5 84 (R)

Office of Superintendent,

May 25- 1917,
R. B. R. Boyershall Superintendent.

WATER REGISTRAR'S OFFICE.

May 22, 1917. 191

To the Superintendent of the New Bedford Water Works:

Please put in a Service upon the Premises described above, and make return of the expense of the same to this office.

C. Baylis
per W. P. Water Registrar.

Bill
5/26/17

16996

Crapo W. side, N. of
Scott

William R. Modesto