

November 9, 1964

#26853

N.B. Institution for Savings

S.E. Cor. #164-74 Union & Purchase Sts.

Please install 2" Copper service to supply bank bldg. To replace 1" Ser.#8530 to be discontinued.

Measures of 2" Curb Stop - Oriseal Valve:

S x S line Union St.	89.1
----------------------	------

W x E " Purchase St.	7.9
----------------------	-----

N x S " Building	3.6
------------------	-----

Main is 40 ft. W x E line

Work done November 9 and 10, 1964

(over)

43' of 2" cop.: 41 out. 2' inside.	98.90
Labor.	126.72
1 2" corporation, fig. 438 - Red Red	
1 2" Mueller Oriseal Valve #H-15201.	
1 R-144 Caldwell Valve Box, complete	
Carting.	10.--
Drilling Machine use	9.--
1 8"x2" 100D. #1159 Dresser Ser. Clamp	
1 2" 450 cop. to cop. elbow.	
1 2" cop. to cop. cplg. A-1671.	
2 st. cuts: 8'x3' & 5'x2' Warrenite	
2 sidewalk cuts: 5' x 4 1/2' Cement.	
Compressor use.	9.--
Loader use.	7.--
Supervision.	22.55

