

Service Leak

N. S. Menton St. E X Lowell St.

Nov. 25, 1966

Ser. #27404-1"

Retapped 6" Cement asbestos main on Menton St.

The above service is now tapped 113.4 ft. E X E line
Menton St. .

This service's new location was necessary due to
main pipe leak.

THIS SERVICE IS IN THE SAME TRENCH AS THE MAIN PIPE

Stock used;

BREAK.

2 ft.-1" Copper tubing

1-1" X 1" cop. to cop. coupling
(located 2ft. N X 1" tap)

The tap is now 1 ft. E X 1" curb stop.

Leclair

P

