Alex X. Leaving Treas

New Bedford Water Works.

SERVICE PIPE RETURN.

| D. No. 36-40 | | |
|---|--|--------|
| For Variport Ubg. Co. No. Prosper | 1 | Persot |
| ou pro | ······································ | rieei. |
| The expense for labor and materials to be paid by the | | |
| applicant is as follows: | | |
| lineal feet of earth excavated at cents per foot, | | |
| lineal feet of rock excavated at cents per foot, | | |
| lineal feet of inch lead pipe at cents per foot, | | |
| 132 lineal feet of 3 inch iron pipe at 29 cents per foot, | 38 | 28 |
| lineal feet of . inch tin lined pipe at cents per foot, | | |
| 1. 3 in gate 1195 1. 3 in rin plag 1. 3 in Sleeve 50 to to 50 1. 75 serew taps 2.50 1. 78 in screw taps | 1 15 | 57 |
| I the second total of 15th 130 minus | | |
| | 11 | 30 |
| Carting 1.00 Loon 20.00 | 21 | 00 |
| | 00 | |
| Proportion of other expenses for putting services into premises, | 7 | |
| Amount, \$ | 86 | 15 |
| | | 7 0 |
| Office of Superintendent. | | |

MBShuman Superintendent.

WATER REGISTRARS OFFICE.

18,00.

To the Superintendent of the New Bedford Water Works:

Please put in a Service upon the premises described above and make return of the expense of the same to this office.

as. Astativaway Water Registrar.

Mer to trad but aft and 1. In some lafe 1.00 Golon Mar Belhumann Superint matent. return at the expense of the same to this office.