

Am W. Hathaway for Water Registrar.

3861

Alfred Allen.

West side of Crapo
South of Washington

lined feet of	inch iron pipe at	cents per foot.
lined feet of	inch iron pipe at	cents per foot.
lined feet of	inch iron pipe at	cents per foot.
lined feet of	inch iron pipe at	cents per foot.
lined feet of	inch iron pipe at	cents per foot.
lined feet of	inch iron pipe at	cents per foot.
lined feet of	inch iron pipe at	cents per foot.
lined feet of	inch iron pipe at	cents per foot.
lined feet of	inch iron pipe at	cents per foot.
lined feet of	inch iron pipe at	cents per foot.

Office of Superintendent.

Superintendent.

WATER REGISTRY OFFICE

To the Superintendent of the New Bedford Water Works:
Please find in duplicate a bill for the water supplied to the above named works.

1871

SERVICE PIPE RETURN

New Bedford Water Works.

Alfred Allen, Water Works
No 3861
New Bedford