New Bedford Water Works. No. 800

RETURN OF SERVICE PIPE.

| ESTATE No. 2 | 70 | 0 | lienth | Street | , for |
|--|-----|-----|---|--------|--------|
| | · · | | Valen an Ju. | | |
| C'11 Or Gall 1 | | | | | |
| Put in by Gifford & allen | | | | | |
| Service Pipe Hinches diameter. August 1871 | | | | | |
| | | | | | |
| Cost to be paid by the City. | | | Cost to be paid by the Proprietor. | | |
| - Cost to no para ny the city. | | | cost to be para by the Proprietor. | | |
| 9665 | 6 | -,0 | 110 0 - | a | C' - I |
| 20.73 lineal feet earth exc. at 2.7cts. | U | 10 | 12.25 lineal feet earth excavated at 23cts. | 2 | 821 |
| lineal feet rock exc. at cts. | | | lineal feet rock excavated at cts. | | |
| | | | | | |
| 1.50 lineal feet lead pipe at 2 cts. | / | 08, | lineal feet lead pipe at cts. | | |
| 9435 lineal feet iron nine at 64rts | 15 | 58 | 5 lineal fact iron pine at 6.4 | A | 9 01 |
| O O | | | 5.—lineal feet iron pipe at 5 4 cts. | 1 | 5 701 |
| Stop Box | 2 | 30 | 1 | | 0 0 0 |
| | | | | | |
| My extended wo | the | 9/4 | lead into the new house | | |
| | | | | | |
| 10 ft further | .// | url | to Oct. 12th 1877 | | |
| • | | | | | |
| | | | | | |
| | | | | | |
| | | | | 7 | 50 |
| | - | | Amount charged Proprietor, | _/ | 5.2v |
| Amount pold by the City | 7.5 | 14 | Total Cost, | 3 2 2 | 66 |
| Amount paid by the City, | 7.0 | | Total Cost, | 02 | 0 0 1 |
| | (| | | | |
| Jarael C. Cornel Superintendent. | | | | | |
| Carrie of Conner Superintendent. | | | | | |

Expense to the City, 25,74

Expense to the Proprietor, 7,52

Total, - - - 32.66

Mater Registrar's Office.

New Bedford, 187/

To the Sup't of the N. B. Water Works:

Please put in a service at the estate named on the back of this Order and return the expense thereof, &c., to my Office.

Water Registrar.