

$$\frac{5}{8} \quad \frac{3}{4} \quad L$$

SERVICE PIPE RETURN.

No. 9263

Off. S. W. cor Cottage & Clinton Street.

15 - 14

253-

.....lineal feet of rock excavated at cents per foot, .

213 -

.....lineal feet of inch iron pipe at cents per foot, .

.....lineal feet of inch tin lined pipe at cents per foot.

Band Lap -

Proportion of other expenses for putting services into premises,

Amount, \$

2	—
6	6 6

Office of Superintendent,

Sept 30, 1897.

R. L. P. Boyeshall

Superintendent.

WATER REGISTRAR'S OFFICE.

Sept. 17' 1897.

To the Superintendent of the New Bedford Water Works:

Please put in a Service upon the premises described above, and make return of the expense of the same to this office.

James Starroway

Water Registrar.

9263

Blanca Le. Gibbs
S. W. cor cottage and
Clinton