

Club 17
shown bath

Connection of
Popes Island Manufg. Co

NEW BEDFORD WATER WORKS.

SERVICE PIPE RETURN.

No. 9559

For Y. M. C. Boat & Canoe Club
Re. N. Side Popes Island Street.

The expense for labor and materials to be paid
by the applicant is as follows:

.....	lineal feet of earth excavated at	cents per foot,	.
.....	lineal feet of rock excavated at	cents per foot,	.
.....	lineal feet of	inch lead pipe at	cents per foot, .
.....	lineal feet of	inch iron pipe at	cents per foot, .
.....	lineal feet of	inch tin lined pipe at	cents per foot,

Proportion of other expenses for putting services into premises, . . .

Amount, \$

Office of Superintendent,

1899.

R. B. P. Boggeshall Superintendent.

WATER REGISTRAR'S OFFICE.

May 16 1899.

To the Superintendent of the New Bedford Water Works:

Please put in a Service upon the premises described above, and make
return of the expense of the same to this office.

Geo. H. Hathaway Water Registrar.
Baylies

9559-

Y.M.C.A. Boat House

Near Tapes Island