

STOP GATE-4" and upward (WASTE)

WG0018
(50A.) STA. 12+08

31-200

FORCE MAIN

St.

Side

St.

Make

Size

4

Set

2003

Box

On

line of

St.

from

line

St.

ft.

from

line

St.

ft.

OPEN TO THE RIGHT

(ON LOCK JOINT MAIN)