
APPLICATION No.: 10496 TAP CLEARED LOCATION: 22 Viall St DATE AFT. REMARKS OWNER: 31-313 MEASURES: 4/10/2019 1" Copper Service Lead Service Line Replacement Program Phase 1, Contractor P Gioioso & Son Type CU, Diameter 1in, Water pressure 100 Distance from main to curb stop (ft) 23 Distance curb stop to meter (ft) N/A Distance from curb face to curb stop (ft) 1 Depth of service (ft) 4 Totallength of new pipe installed (ft) 23 Curb stop replaced: Yes size 1" Corporation replaced: Yes size 1" Ball valve replaced: No



. 9 martin 993 9411 APPLICATION No.: 10496		TAP	CLEAR	RED 8645-3821
LOCATION: 22 Vial1	DATE	BEF.	AFT.	REMARKS
OWNER: J &JH Duchsworth	11/7/86:	TAP	REAMED	86-31-2308
MEASURES: 311			8/15	86-33-1080
				8709-0641
N from E Viall 8.5 ct.				
S from N house				
Renewed from ½' outside curb stop to prop line.				
Stock: 7ft. 3/4" copper tubing 1 - 3/4" curb stop 1 - caldwell stop box 2 - 3/4 x 5/8 lead to cop adapt. xs.				
OWNER WOULD LIKE RENEWAL WAS TOLD TO CHECK WITH US LATER IN YEAR				
TO CHECK WITH US LATER IN YEAR			E	
(TOO HEAVY WORK LOAD) S.R.				
11/7/86: JRenewed from main to a point 1 ft. Stock: 1ft 3/4"				
copper tubing $1 - 3/4 \times 5/8$ lead to cop adapt. xxs $1 - 3/4 \times 5/8$	Fig. 41	3		
NOTE: 5/8" tap not 1/2" ====================================				
2/25/87: Renewed from ½' outside curb stop to inside cellar. Stock: 14ft. 3/4" copper tubing (8' ins.)				
=======================================				
				1

METER HISTORY						CHARGE OUTS.				
DATE	SET	SIZE	MAKE	NUMBER	READING		TEST		REMARKS .	
9/2/37			Hersey	1705988						
3/4/31		0/0	ersey	1109990						
									No.	
						-				
					1					
	-	179							*	
-								-		
							-			
						1				
									12.02.00	
					4.9					
									P	
					,					
									a di constanti di	
	-								Y.A.	