

12087

23 Independent St

OWNER:

31-313

April 23, 1908

179.0 ft

8.0 ft

11.0 ft

16.0 ft

12.0 ft

6.0 ft

32.0 ft

1" Copper Service

11/26/2018 Lead Service Line Replacement Program

PHase 1, Contractor P Gioioso &amp; Son

Type CU, Diameter 1in, Water pressure 100

Distance from main to curb stop ft 25

Distance from curb stop to meter ft 14

Distance from curb face to curb stop ft 2.0

Depth of service ft 4.0

Total length of new pipe installed ft 25

Curb stop replaced: yes size 1"

Corporation replaced: yes size 1"

Ball valve furnished: no size 3/4"

Remarks: 1-3/4" union installed 1LF outside curb stop

[illegible]