

12166

362 Earle St

OWNER:

31-313

06/14/2018 - Lead Service Line Replacement
Program, Phase 1, Contractor P Gioioso & Son
Type CU, Diameter 1in, Water pressure 70
Distance from main to curb stop (ft) 11.0
Distance from curb stop to meter (ft) N/A
Distance from curb face to curb stop (ft) 3.
Depth of service (ft) 3.5
Total length of new pipe installed (ft) 11.0
Curb stop replaced: yes, size 1"
Corporation replaced: yes, size 1"
Ball Valve Furnished: No

TAP CLEARED

DATE _____

BEF.

AFT.

REMARKS

[illegible]

APPLICATION No.: 12166

TAP CLEARED

LOCATION: 362 Earle
OWNER: Lawrence Ras

DATE BEF. AFT. REMARKS

12/5/56

reamed

MEASURES:

5/8" Change over to 3/4 Meter 5-10-65

E from	Church	181.5
N from S line	Earle	9.0
E from W line	House	4.8

May 10, 1965 Renewed service from 3 ft. inside curb stop to meter
inside cellar 11 ft. 3/4" copper tubing
3/4" copper coupling, A-1525

Dec. 5, 1965 Renewed from main to a point 4 ft. inside curb stop
13 ft. of 3/4" copper tubing 3/4" copper to I. F. Cplg., fig.
3/4" copper stop, fig. 415 - R. H. 413
1 lb. wiping solder

[illegible]

CHARGE OUTS

[illegible]