

TAP CLEARED \$245.0008

LOCATION: 48 Briggs St.

OWNER: Joseph & Virginia Sylvia

MEASURES: 5/8" H lead Aug. 18, 1908

N from Thompson St. 177.0 ft.

W from E line Briggs St. 9.0 ft.

S from N line house 13.5 ft.

NOV 8 1982 --Renewed from main to a point 5 ft. from main.
5.0 ft.-3/4" copper; 5/8" x 3/4" Fig. 413; 5/8" x 3/4"
lead-cop. adapt. XXS;

JUN 16 1983 -- Renewed from main to a point 7.7 ft. from main. 7.7 ft.-3/4" copper; Same Fig. 413; 5/8" x 3/4" lead-cop. adapt. XS;

6/4/84 - Renewed from main to property line.
26 Ft. - 3/4" copper tubing; 1 - 3/4" curb stop;
1 stop box; 1 - 3/4" x 5/8" lead to copper adapt. XXS

5/21/2019: Lead service line replacement program phase 1

Contractor: P. Gioioso & Sons Inc.

Type: CU, Diameter 1", Water Pressure 100

Distance curb stop to meter 16'

Distance from curb face to curb stop 2'

Depth of service 4'

Total length of new pipe installed 16'

Curb stop replaced NO:

Corporation replaced NO.
Bam valve replaced NO

Ball valve - replaced NO
furnished yes size 1"

distance from main to curb stop (4) 104

BRADBURY-WARING, INC.

DATE _____

BEF.

AFT.

REMARKS

NOV 8

1982

Reamed

JUN 16 1983

Reamed

6/4/84

REAMED

[illegible]

CHARGE OUTS

