

12486

367 Earle St

OWNER:

31-313

SURES: 06/18/2018 - Lead Service Line Replacement  
Program, Phase 1, Contractor P Gioioso & Son  
Type CU, Diameter 1in, Water pressure 70  
Distance from main to curb stop (ft) N/A  
Distance curb stop to meter (ft) 16.0  
15 ft to house + 1 ft wall  
Distance from curb face to curbstop (ft) 1.5  
Depth of service (ft) 3.4  
Total length of new pipe installed (ft) 19  
16 ft + 3 ft whip  
Curb stop replaced: no  
Corporation replaced: no  
Ball Valve Furnished: yes size 1"

TAP CLEARED

DATE \_\_\_\_\_


BEF.

AFT.

REMARKS

[illegible]

CHARGE OUTS.





APPLICATION No.: 12486

TAP CLEARED 8319-1267 ✓

LOCATION: 367 Earle

OWNER: John Brinds

MEASURES:

5/8"

E from	Church	148.0
S from N line	Earle	9.0
E from W line	House	3.0

MAY 12 1983 --Renewed 6" outside curbstop to 6.0 ft. inside  
(property line.) 7.6 ft. -3/4" copper; 3/4" curb stop;  
stop box; 2- 5/8" x 3/4" lead-cop. adapt. XS;

10/13/04 Renewed from main to curb stop. Stock: 25 ft. 3/4"  
copper tubing; 3/4" curb stop; Caldwell stop box; 5/8" x 3/4" Fig.  
413 Tap reamed  
-----

DATE

BEF.

AFT.

REMARKS

10/13/04

Tap Reamed

## METER HISTORY

[illegible]

## CHARGE OUTS