		APPLICATION No.: 12576				TAP CLEARED				
LOCATION:_	13 Viall			DATE	BEF.	AFT.	REMARKS			
OWNER:	34									
	The second secon				,					
MEASURES:	5/8"									
	S from	0	223							
	E from W	Cove Viall	211.5 ft.				7.4			
	S from N	House	9.0 ft. 11.8 ft.							
8/27/79: R	enewed 6" outsic	le curbstop to i	nside cellar.							
18 ft3/	4" copper (8 ft.	ins.); 5/8" x	3/4" lead-cop.							
adapt. XS;	3/4" curb stop;	Caldwell stop	box							
May 21 19	98 Checked sidewalk	cut - W Dichmon	d one cause brok	on no	nonont	of wo	nk dono			
looks like	dug by hand around	stop box & new bo	x - Cement sq. adde	d to 97	list	OI WO	irk done -			
4/10/	2019 1" Copper S	ervice		00 37	LISU.					
Lead	Service Line Rep	lacement Progra	m							
Phase	1, Contractor P	Gioioso & Son	100							
Dista	CU, Diameter 1in nce from main to	curb stop (ft)	e 100							
Distar	nce curb stop to	meter (ft) N/A					`			
Distar										
Depth	of service (ft)	5	C1 \ 4.4							
Curb	length of new p stop replaced: Y	es size 1"	It) 11							
Corpo	ration replaced:									
Ball	valve replaced:	No			-	,				
				1						

METER HISTORY								CHARGE OUTS		
DATE	SET	SIZE	MAKE	NUMBER	READING		TEST	REMARKS		
4/3/70		5/8	" Trid Mg.	16722467					The state of the s	
						-				
								28' 23'		