

APPLICATION No.: 12771

TAP CLEARED

LOCATION: 74 Division St.OWNER: Joseph Cournoyer Et UxMEASURES: 5/8" H lead July 1, 1909E from Sounty St. 110.4 ft.N from S line Division St. 7.0 ft.E from W line house 12.8 ft.Nov. 6, 1970 Renewed from 5 ft. outside curb stop to cellar23 ft. - 3/4" copper tubing (15 ft. inside)3/4" Rays curb stop 1 wipe joint 2-3/4" meter cplg.01/08/2019 Lead service line replacement programPhase 1, Contractor P Gioioso & Son 1" Copper ServiceType CU, Diameter 1in, Water pressure 90Distance from main to curb stop (ft) 12Distance from curb stop to meter (ft) N/ADistance from curb face to curb stop (ft) 2Depth of service (ft) 4Total length of new pipe installed (ft) 12Curb stop replaced: yes size 1"Corporation replaced: yes size 1"Ball Valve Furnished: no

DATE

BEF.

AFT.

REMARKS

METER HISTORY

CHARGE OUTS

DATE	SET OUT	SIZE	MAKE	NUMBER	READING	TEST			REMARKS

2-
5/31/62

11/6/70

