

APPLICATION No.: 142 89
Box

LOCATION: 1560 E.S.E. French Ave.

OWNER: Frank Travers

MEASURES:

5/8"

August 13, 1963 Repaired leak in inside joint of curb stop by tightening the nut.

NOT READING 8/27/2009

[illegible]

CHARGE OUTS

[illegible]