

APPLICATION No.: 15470

TAP CLEARED

23519

LOCATION: 248 Whitman S.S.W. of Bowditch

OWNER: Joseph W. Grimshaw

MEASURES: W from Bowditch 247.0 ft.
N from S Whitman 8.5 ft.
E from W house 14.0 ft.

DATE BEF. AFT. REMARKS

8/11/88: TAP REAMED

8832-1209

July 23, 1968 Renewed from $\frac{1}{2}$ ft. outside curb stop to a point 6 ft. inside the curb stop.

$6\frac{1}{2}$ ft. of $\frac{3}{4}$ " copper tubing used. Total.

1 $\frac{3}{4}$ " Mueller curb stop 2 wipe joints.

Dec. 30, 1980: Renewed from main to the curb stop.

9.0 ft. $\frac{3}{4}$ " copper

1- $\frac{3}{4}$ " Stop box Reused $\frac{3}{4}$ " curb stop

1- $\frac{5}{8}$ " x $\frac{3}{4}$ " Fig. 413 Tap reamed

8/11/88: tap reamed-----Stock: 1- $\frac{3}{4}$ x $\frac{3}{4}$ cop to cop cplg. comp.

1" Copper service 4/27/2018

Lead Service Line Replacement Program

Phase 1, Contractor P Gioioso & Son

Type Cu, Diameter 1in, Water pressure 60

Distance from main to curb stop (ft) N/A

Distance from curb stop to meter (ft) 17

Distance from curb face to curb stop (Ft) 3

Depth of service (ft) 3.5

Total length of new pipe installed (ft) 20

Curb stop replaced: NO Corporation replaced: no

Ball valve replaced: yes size 1"

METER HISTORY

DATE	SET OUT	SIZE	MAKE	NUMBER	READING	TEST			REMARKS
6/18/68		5/8	Rock Mg.	20095377					

CHARGE OUTS

