	APPLICATION No.: 15499		TAP CLEARED			
LOCATION: 76 Scott St.	1		DATE	BEF.	AFT.	REMARKS
OWNER: Antonio Medeiros						
MEASURES:						
5/8"	H lead	Dec.1,1913				
E from	Crapo St.	416.0 ft.				
N from S line	Scott St.	9.0 ft.	-			
W from E line	hoùse	3.5 ft.				111111111111111111111111111111111111111
Aug. 19, 1976 Renewed frinside cellar. 20 ft 3/4" Copper tubin 3/4" Curb stop 3/4" lead to copper adapt 1" Copper Service - 07/02/2019 Lead Service Phase 1, Contractor P Type CU, Diameter lin, Distance from main to Distance from curb sto Distance from curb face Depth of service (ft) Total length of new picurb stop replaced: Ye Corporation replaced: New Yellowship Reservice (ft) Ball valve replaced: New Yellowship Reservice (ft)	caldwell Stop Bor XS ce Replacement Pro Gioioso & Son Water pressure curb stop (ft) 13 op to meter (ft) 15 ce to curb sop (Ft) 4 ope installed (ft) es size 1" Yes size 1") ox ogram 100 2 N/A t) 1				
BRADBURY-WARING, INC.				10.		7

