

15538c

APPLICATION No.: 15

TAP CLEARED

620 (rear) So. First
LOCATION: _____

OWNER:

MEASURES:

Conn. of 5212

DATE _____

BEF.

AFT.

REMARKS

[illegible]

CHARGE OUTS

[illegible]

Dec. 8, 1913. This service
now supplies 620 So. First
by connection #15538, and
626 So. First by connection
#15537, as shown.

Nov. 19, 1946
Repaired service leak using
26' 5/8 Lead pipe; 1 new
Red Hed Curb stop.

Scale 1 in = 24 ft.

