APPLICATION No.: 15793	TAP CLEARED /				
LOCATION: 95 Richmond	DATE	BEF.	AFT.	REMARKS	
OWNER: Robtialle	4/14/97			971505(22	
MEASURES:					
3/4 ^{tt} S from William					
From William 24.0 E from W line Richmond 9.0					
N from S line houss 8.7					
MAY 24 1982 Tilcon renewed from the main to the curb st 16.0 ft3/4" copper; curb stop; stop box; 1" x 3/4" Fig:	op.				
413; 5/8" x 3/4" lead-cop. adapt. XXS;			1		
April 10,1997 LEAD SERV.REPLACEMENT Renewed from curb stop to prop line				- 1	
Stock: 7ft 3/4" copper tubing same curb stop					
1- 3/4 x 5/8 lead-cop adpat.xxs(USED SAME ONE)					
				and a second	

METEI	R H	ISTO	DRY							CHARGE OUTS
DATE	SET	SIZE	MAKE	NUMBER	READING	9	TEST		REMARKS	
0.7.04			Musidant No.	16811902				_		
2=3=64			Trident Mag	10011902						
							/20			
										W 1
										No.

95 WILLOW APPLICATION No.: 15793	TAP CLEARED				
LOCATION: 95 Reihmond S.W.Cor. Willow	DATE	BEF.	AFT.	REMARKS	
OWNER:					
MEASURES:					
3/4"					
S from Willow 24.0 ft.					
E from W Richmond 9.0 ft. N from S house 8.7 ft.					
N from S house 8.7 ft.					
MAY 7 1982 Tilcon renewed from the main to the prop.					
line. 18.0 ft3/4" copper; 3/4" curb stop; stop box; 1" x 3/4" Fig. 413; 5/8" x 3/4" lead-cop. adapt. XXS;					
1" x 3/4" Fig. 415; 5/0 x 5/4 Tead-cop. adapt. Axo,					
				Kill Landson	

METE	RH	IISTO	ORY				1,			CHARGE OUTS
DATE	SET	SIZE	MAKE	NUMBER	READING		TEST		REMARKS	
						10				
							-			
	-		,				-	-		
						-	-	_		
			I I							
							-			
						-	-			
							-			
-						-	-	-		
									# hardy could be	
									Market Control	
							-			
and the same of the same of	2.3.		the same of the same of the same of				200	Marie Co.		