| | V APPLICATION No.: 16421 | | | TAP CLEARED | | | |
|---|--------------------------|-------------|---------|-------------|--------|---------------|--|
| LOCATION: 601-3 So. Se | | 5,5 | DATE | BEF. | AFT. | REMARKS | |
| OWNER: Donat Boisvert | | | | | | MAP. | |
| MEASURES: | | | | | 1 | off of Molson | |
| 5/8" | H lead | Oct.19,1915 | 1 - | | 1-14- | 9303 2033 | |
| W from | So.Second St. | 34.3 ft. | 1/14/93 | tap | reamed | | |
| N from S line | Nelson St. | 9.0 ft. | | | | | |
| W from E line | garage | 33.0 ft. | | | | | |
| 1/14/93: Renewed from main to prop line Stock: 18ft 3/4" copper tubing 1-3/4" curb stop 1-Caldwell stop box 1-3/4x5/8 lead-cop adapt.xxs 1-3/4x5/8 Fig 413 1" Copper Service 1/9/2019 Lead Service Line Replacement Program Phase 1, Contractor P Gioioso & Son Type CU, Diameter 1in, Water pressure 100 Distance from main to curb stop (ft) N/A Distance from curb stop to meter (ft) 17 Distance from curb face to curb stop (ft) 2 Depth of service (Ft) 4 Total length of new pipe installed (Ft) 17 Curb stop replaced: No Corporation replaced: No Ball valve replaced: Yes size 1" | | | | | | 1 | |
| | | | | - | | | |
| | | | | | | | |
| | | | | | | | |
| | | | * ** | | | | |
| | | | | · · | | | |
| | | | | | | | |
| | | | | | | | |
| | | | | | | | |
| | | | 7 | | | | |
| | | | | | | | |
| | | | | | | | |
| | | | | | | | |
| | | | | | | 3 6 6 6 6 | |
| BRADBURY-WARING, INC. | | | | | | | |

