

Replaced 2" L. Lead with 5/8" H. Lead, Using 16' pipe 4.48 -----16 - 5/8H. Lead 1 5/8 Stop 5-2-39 1# Solder 12/3/66, shut off at corp tap & coupling & stop box (complete) were removed-and-returned to the repair shop. Pipe was abandoned in ground.