


APPLICATION No.: 1944TAP CLEARED LOCATION: 160 Grinnell St.OWNER: Edward FortesMEASURES: 5/8" H lead Oct. 7, 1874W from County St. 279.8 ft.N from S line Grinnell St. 6.9 ft.W from E line house 7.4 ft.

Aug. 3, 1972 Renewed from $\frac{1}{2}$ ft. outside curb stop to inside cellar
15 ft. - $\frac{3}{4}$ " Copper tubing (8 ft. ins.)
 $\frac{3}{4}$ " Hays curb stop 1 wipe joint

June 23, 1995: Renewed from main to curb stop
Stock: 7ft $\frac{3}{4}$ " copper tubing 1- $\frac{3}{4}$ " curb stop
1- Caldwell stop box 1- $\frac{3}{4}$ x $\frac{5}{8}$ lead-cop adapt.xxs 6 in in front
of tap

=====

Sept 7, 1995: Leak at tap Coupling loose
Dug street & Tightened coupling

DATE

BEF.

AFT.

REMARKS

95 2506342

6/26/95: tap reamed 953603572

[illegible]

CHARGE OUTS

[illegible]