

APPLICATION No.: 21766

TAP CLEARED ✓LOCATION: 463 Morton Ave. oppo Ivers St.OWNER: Eugenia R. GrenfieldMEASURES: $3/4"$

S from

E from W line

S from S line

H lead

Ivers

Morton Ave.

House

5-23-39

44.8 ft.

8.6 ft.

13.0 ft.

DATE

BEF.

AFT.

REMARKS

4-29-
93

9353 02035

11/29/0 8:002010-4900540

May 19, 1994 Owner complaint of sidewalk lifted after main break on Oct. 1993
 lifted about 4" & cracked.

checked by Hansen - Reported 5' x 5' Cement Sq. & 5' x 4' Cement Sq. - Added to cut list

11/30/10 - City crew renewed water service from main to
 property line

14 ft - $3/4"$ copper tubing; 1 - $3/4"$ curb stop; 1 Caldwell
 stop box; 1 - $3/4"$ x 1" lead to cop adapter xxs; 1 - $5/8"$ x

$3/4"$ Fig. 413; Tap cleaned. Foreman: Felix Fernandez

1" Copper Service

11/30/2017 Lead Service Replacement Program, Phase 1

Contractor P Gioioso & Son, Type CU, Diameter 1in, Water pressure 65

Distance from main to curb stop (ft) N/A

Distance from curb stop to meter (ft) 50.6

Distance from curb face to curb stop (ft) 3.0

Depth of service 4.2

Total length of new pipe installed (ft) 50.6

Curb stop replaced: No Corporation replaced: no

Ball valve replaced: yes size 1"

Remarks: curb stop new connected new 1" cu to existing w/ $3/4"$
 adpt

METER HISTORY

CHARGE OUTS

DATE	SET OUT	SIZE	MAKE	NUMBER	READING	TEST			REMARKS
6-10-39		3/4	Hersey D	1757932					

