

Service removed - Dec. 3, 1963 - was completely removed, shut off at tap, connection cut off, lead pipe and stop box were removed. Now supplied by Ser. #26228.