

23141

✓

132 Topham St., W of Harvard St.

Lester L. Brown

3/4"	Copper	July 6, 1950
W from W line	Harvard	45.0 ft.
N from S line	Topham	5.0 ft.
E from W line	house	19.6 ft.

2 ft. - 3/4" Copper tubing
3/4" Dresser cplg.

May 30, 1984 - replaced stop box
1 - #1 stop box complete

7/27/94 No leak found at this time M. Rose

2/8/08 - Service renewed from main to curb stop (was
leaking at tap)
7 ft -3/4" copper tubing;1 -3/4" curb stop;1 -3/4" Fig 413;
Tap reamed (Foreman: Dennis Monty reported still leaking
inside property -18 ft punch, fence would need to be
removed, service under porch,walkway settling)
referred to hire a bonded contractor

2/14/08 - Owner charged \$130.00 (\$30 for shut off, \$70 for inspection & \$30 for turn on). Inspected by Percy R

2714708 - Nelson Cardoso renewed service from curb stop
to inside cellar. Used 26 ft -3/4" copper tubing;
Inspected by Percy Reynolds

[illegible]

CHARGE OUTS

[illegible]