	APPLICATION No.: 2485	TAP CLEARED			
LOCATION:_	154 Grinnell St	DATE	BEF.	AFT.	REMARKS
OWNER: _					
	June 3,1876 W from County St 141.0' N from S Line Grinnell St 6.7' W from E Line house 9.2' 9-25-2018: Lead service line replacement programse1, TYPE CU, Diameter linch, Water Pressur Distance from main to curb stop 7' Distance curb stop to meter 17.5' Distance from curb face to curb stop 1.8' Depth of service 4.0' Total length of new pipe installed 17.5' Curb stop replaced: NO Size 3/4" Corporation replaced: NO Size 3/4" Ball Valve furnished: YES Size 1" Remarks: 1- 3/4" installed 1.0 LF outside curb	4/21/53 reamed			
		am e 80			
		stop			

