

22 Tarkiln Hill Rd.

October 26, 1973

#29002

D. J. Realty Corp.

N.S. Townsend St., E. x Easton St.

Please install 1" copper service to supply
ranch. Meter inside cellar wall above floor.
Service from Townsend St. Lot 59

ord - per M. Guineau
M.T.

