NOT IN SERVICE APPLICATION No .: 29077		TAP	CLEAR	RED V						
LOCATION: E.S. Chancery St. S x Ash St.	DATE	BEF.	AFT.	REMARKS						
OWNER: United Front Homes										
	0, 1973									
S from S line Elm St. 76.0 ff E from W line Chancery St. 18.0 ff N from S line Bldg. 9.2 ff W from E line Chancery St. 26.3 ff	t									
June 19, 1974 Frederico Const. Co. renewed 4" s from a new 12 x 12 x 6" tee in Chancery St. 12" x 12" x 6" Cast iron C.L. tee - Mech. Jt.		der o	Ins	tallation:						
l ft 6" C.I.C.L. Pipe	12	2" x 1:	2" x	6" Tee						
6" x 4" C.I.C.L. Reducer - Mech. Jt. 4" Mueller gate valve - Mech. Jt.		Pipe	le .							
2 ft 4" C.I.C.L. pipe	6"	x 4"	Reduc	er						
4" Solid Sleeve - Mech. Jt.		Priva								
4" round iron gate box, reused The old 4" bell joint gate valve returned to sho	p. 2	ft	LII P	pe						
Measures of new 4" Gate Valve), 11	Dress								
S x S line Elm St. 75.0 ft. E x W line Chancery St. 19.0 ft.			*							
Measures of Reducer 6" x 4"										
S x S line Elm St. 75.0 ft. E x W line Chancery St. 17.0 ft.										
May 23, 1975 Repaired aleak on the 4" C.I. ser by installing a #227 Repair Sleeve. 1 -4" Smith Blair Repair Sleeve #227 62" wide(ncery	St. 1	0 ft.)						

METER HISTORY							CHARGE OUTS			
DATE	SET	SIZE	MAKE	NUMBER	READING		TEST		REMARKS	
								- 112		
_	-									
					j.					
-										