

APPLICATION No.: 3540

TAP CLEARED

LOCATION: 185 County St

OWNER: 1

31-313

MEASURES:

5/22/2019 - Lead Service Line Replacement Program
Phase 1, Contractor P Gioioso & Son
Type CU, Diameter (in) 1, Water Pressure 100
Distance from main to curb stop (ft) n/a
Distance from curb stop to meter (ft) 21
Distance from curb face to curb stop (ft) 2.8
Depth of service (ft): 4
Total length of new pipe installed (ft) 21
Curb stop replaced: no, corporation replaced: no
Ball valve replaced: yes, size 1"

DATE

BEF.


AFT.

REMARKS

METER HISTORY

CHARGE OUTS

DATE	SET OUT	SIZE	MAKE	NUMBER	READING	TEST			REMARKS



Remarks

APPLICATION No.: 3540

TAP CLEARED

LOCATION: 185 County St.

OWNER: Mary S. Furtado

MEASURES: $\frac{1}{2}$ " H lead Nov. 24, 1879

S from Thompson St. 20.9 ft.

E from W line County St. 8.2 ft.

N from S line house 9.3 ft.

Mar. 4, 1966 Rewiped joint at the main
1 lb. wiping solder

April 30, 1975 Renewed from the main to the property line.

✓ 16 ft. - 3/4" Copper tubing
Caldwell Stop Box
3/4" x 3/4" Fig. 413

3/4" Curb stop
3/4" x 1/2" bushing
5/8" x 3/4" lead conn.

Owner refused to renewe service

BRADBURY-WARING, INC.

[illegible]

CHARGE OUTS

[illegible]