

462



OWNER:

31-313

08.16.2018 - Lead Service Line Replacement Program
Contractor - P. Gioioso and Sons
Type: CU, Diameter (in) 1, Water pressure (PSI) 90
Distance from main to curb stop (ft) 8.2, Distance
curb stop to meter (ft) 15.5, Distance from curb
face to curb stop (ft) 1.5, Depth of service (ft) 4.3
Total length of new pipe installed (ft) 8.2
Curb stop replaced: Yes Size 1"
Corporation replaced: Yes size 1"
Ball Valve Furnished: 3/4"
REmarks: 3/4-1" union installed 1.0 ft outside curb
stop

Service Place: Oct 10, 1870

S from Forest St. 33.8 ft

E from W Line Bonney St 6.9 ft

S from N line house 10.9 ft

CHARGE OUTS

[illegible]