

LOCATION: 620-6 First APPLICATION No. 5212
Meter in 624

OWNER: Jeklor Grsebrien

MEASURES:

 $\frac{1}{2}$ II

Shut off & removed 6-11-62

N from	Blackmer	77.9
W from E line	Rirst	6.5
N from S line	House	2.6

W from E line Rirst 6.5

N from S line House 2.6

To be killed

Sept. 1999 - Per Felix Fernandez - Could not find service.

INACTIVE SER

TAP CLEARED

DATE _____

BEF.

AFT.

REMARKS

[illegible]

CHARGE OUTS

[illegible]

15538c

APPLICATION No.:

LOCATION: 620 (rear)

So. first

TAP CLEARED

DATE

BEF.

AFT.

REMARKS

OWNER:

MEASURES:

Conn. of 5212

[illegible]

CHARGE OUTS

[illegible]

APPLICATION No.: 15537a

TAP CLEARED

LOCATION: 626 So. First

OWNER:

MEASURES:

Conn. of 5212

DATE

BEF.

AFT.

REMARKS

[illegible]

CHARGE OUTS

[illegible]

Dec. 8, 1913. This service
new supplies 620 So. First
by connection #15538, and
626 So. First by connection
#15537, as shown.

Nov. 19, 1946
Repaired service leak using
26" 5/8 Lead pipe; 1 new
Red Hed Curb stop.

Scale = 1 in = 24 ft.

