

APPLICATION No.: 6382

TAP CLEARED

LOCATION: 120 Division St.OWNER: Belmira & Louise CostaMEASURES: $\frac{1}{2}$ " H lead Apr. 11, 1890

W from County St. 200.3 ft.

N from S line Division St. 6.4 ft.

E from W line house 10.3 ft.

8/15/78: Renewed from main to 4 ft. front of main.

4 ft. - $\frac{3}{4}$ " copper; $\frac{5}{8}$ " x $\frac{3}{4}$ " Fig. 413; $\frac{5}{8}$ " x $\frac{3}{4}$ " lead
to copper adapt! XXS;11/18/97: renewed from $\frac{1}{2}$ ' to outside curb stop to prop. line.
Stock: 7 ft. $\frac{3}{4}$ " copper tubing, 1- $\frac{3}{4}$ ' curb stop, 1 #1 Caldwell
stop box, 2- $\frac{5}{8}$ x $\frac{3}{4}$ lead to cop. adapt.xs11/14/97 - CURB STOP LEAK =====

4/12/06 Renewed from main to property line

Stock: 8' of $\frac{3}{4}$ " copper tubing, $\frac{3}{4}$ " curb stop, stop box,
 $\frac{5}{8}$ x $\frac{3}{4}$ Fig. 413, tap reamed

DATE

BEF.

AFT.

REMARKS

8/15/78

Reamed

11/18/97974701644

4/12/06

Tap Reamed

[illegible]

CHARGE OUTS

APPLICATION No.: 6382

TAP CLEARED

LOCATION: 120 Division St

OWNER:

31-313

MEASURES:

3/4"

Copper

W from W line	County St	201.0
N from S line	Division St	5.2
E from W line	House	10.0
W from E line	House	15.0
N from N line	House	13.8
Pipe inside P roperty Line		10.0

10/22/08 - Nelson Cardoso renewed service from 2' outside property line into cellar. Inspected by Percy Reynolds
Owner charged \$100 (\$70 Inspection & \$30 turn-on fee)

DATE

BEF.

AFT.

REMARKS

[illegible]