

8-28-51, ser leak, replaced old lead pipe from tap to cellar inside using 32 ft. 3/4" copper tubing type K, soft. Bill No. 47069. Tap reamed. 5/8" tap at main. Pipe formerly went through manhole. Now pipe laid around the northside of the manhole. 2/2/67, shut off at the corp. tap; coupling was removed and returned to repair shop; stop box & pipe abandoned in ground.