

APPLICATION No.: 7411 $\frac{1}{2}$ " H lead

TAP CLEARED

LOCATION: 204 Belleville Ave.

DATE

BEF.

AFT.

REMARKS

OWNER: Albert Soares

7/17/63

Reamed

MEASURES: $\frac{1}{2}$ " H lead Oct. 29, 1892
 S from Sawyer ~~85.6 ft.~~ 86.6 ft.
 W from E line Belleville Ave. ~~7.0 ft.~~ 8.6 ft.
 N from S line House ~~11.4 ft.~~ 11.0 ft.
 W x W line House 15.5 ft.

Sept. 29, 1954 Renewed from a point 6" outside curb stop to inside cellar.

18 ft. - $\frac{3}{4}$ " copper tubing; 1- $\frac{3}{4}$ " copper stop, fig. 415; 1 wiped joint.

August 11, 1958 Rewiped joint at a point $\frac{1}{2}$ ft. outside of curb stop to curb stop. $\frac{1}{2}$ ft. - $\frac{3}{4}$ " copper tubing type K, soft; 1# wiping solder;

July 17, 1963 Rewiped joint at main.
 1 wiped joint; Tap reamed.

7/9/76: Due to the inst. of the new 48" main this service has been renewed from the main to 20 ft. from the main. Stock supplied & inst. by Zoppo. 20 ft. - $\frac{3}{4}$ " copper tubing; 1" Corporation Ford Compression;

1" x $\frac{3}{4}$ " Reducer, $\frac{3}{4}$ " curb stop Ford comp; $\frac{3}{4}$ " x $\frac{5}{8}$ " cop to lead adapt. XKS
Measures of 1" Corp: S x S line Sawyer 85.6 ft. - W x E line Belleville Ave. 29 ft.

METER HISTORY

CHARGE OUTS

[illegible]This image shows a blank, aged, cream-colored page, likely an endpaper or flyleaf of a book. The paper has a slightly textured appearance with some faint smudges and discoloration, characteristic of old paper. The left edge of the page shows the binding structure, including the stitching or glue binding. There is no text or other markings on the page.