

APPLICATION No.: 8798

TAP CLEARED ✓

LOCATION: 21 EMERSON ST

OWNER: JOHN T CURRY JR

MEASURES: 5/8"

N FROM ARNOLD ST 195.3 ft

E FROM W LINE EMERSON 6.1 ft

N FROM S LINE HOUSE 6.0 ft

April 11, 1997: Street reconstruction

Renewed from main to curb stop

Stock: 8ft 3/4" copper tubing same curb stop
same Caldwell stop box =====

7/5/16 c/s to meter

1 ft 3/4" 90° copper elbow

1 ft 3/4" threaded copper

1 ft 3/4" ball valve

21 ft 3/4" copper tubing

lead worker : Ronald Aguiar DPI

DATE

BEF.

AFT.

REMARKS

4/11/97: tap reamed

METER HISTORY

[illegible]

CHARGE OUTS

This image shows a blank, aged, cream-colored page, likely an endpaper or flyleaf of a book. The paper has a slightly textured appearance with some faint smudges and discoloration, characteristic of old paper. The left edge of the page shows the binding of the book. There is no text or other markings on the page.

APPLICATION No.: 8798

TAP CLEARED 8710-0735

LOCATION: 21 Emreson

OWNER: John T. Curry Jr.

MEASURES:

5/8"

N from	Arnold	195.3
E from W line	Emerson	6.1
N from S line	House	6.0

Nov. 22, 1949 Leak at tap.
3 ft. of 3/4" copper tubing

3/4/87: Renewed from 1/2' outside curb stop to prop line.
Stock: 6.0ft. 3/4" copper tubing 1-3/4" curb stop
1 - Caldwell stop box 2-3/4 x 5/8 lead to cop adapt. xs.

Nov 11, 1996: During cement lining & replacement of new hydt
new 3/4 tap was tapped on new piece pipe D.I. 2ft S x hydt tee
REnewed from main to a point 2ft in front of main
Stock: 2ft 3/4" copper tubing 1-3/4x5/8 lead-cop adapt.xs
1- 3/4" corporation tap Insp. F Bento
Biszko Cont. C.L. area

[illegible]

CHARGE OUTS

[illegible]