

✓
DRAIN

Second St.

South to Grinnell

Enters Second St lower.


abt. 93.6' sof Grinnell, 6" p. March 25 1901 at
1 P. M. by F. L. Le Mello

From property of Lloyd N. Pierce Est

Located Second Ins 94.8 sof Grinnell

Account Misc. Ledger p 56

7/2/84



REVISION NOTE: EXISTING SEWER
CONNECTION TIED INTO NEW
8" SEWER PIPE (APRIL 1984)