
151.12
N.S. CTRS REDSON ZIS CO'S
NEW OFFICE BLDG.
TO ELEVATOR
ENTRANCE
TO GARAGE
PURCHASE ST.
42.70
.67 = 8" wall of MH.
FINAL 43.37 PER DUCT.
U.S. RY. CO TRACKS
TO SCHOOL ST
MH 4x4x4.5
40.25 Tee Duct
90.50 both Ducts.
From ℄ of COVER of MH.
TO SPRING ST.
FIBRE DUCT
THIS DUCT DEAD ENDED.
EAST SIDEWALK
MURPHY'S STABLE
LOWE'S GARAGE
POINT OF ENTRANCE SHOWN ON LARGER SCALE.
Bead - Length 1.63 Chord 1.61 Rise 0.13
40.03
1.63
41.66 = 3" h. pipe
1.09.3 Galv.
42.70
2.58 From
45.25 ℄ MH to New Office Bldg. SERVICE Box.
Plotted


21.5
37.40 TO MURPHY'S STABLE
THERE ARE 4-3" FIBRE DUCTS.
SOUTH DUCT IS A SERVICE DUCT FOR MURPHY'S STABLE - THE NORTH DUCT IS DEAD ENDED.
THE TWO TOP DUCTS ARE DEAD ENDED APPROXIMATELY OPP MURPHY'S SERICE. (COVERED WHEN I GOT THERE)
THEY ARE FOR PURCHASE ST
FUTURE SERVICE. LENGTH PER DUCT = 21.5 + 5 = 26.5±
SOUTH.
SERVICE TO MURPHY'S STABLE AND FUTURE GARAGE.
MURPHY'S STABLE
DEAD ENDED.
A 4 FT.-3" RISER PIPE.
FOR CONNECTION.
STONE WALK. (EAST SIDEWALK)
TO SCHOOL ST.
TO SPRING ST.
(NEW LOWE'S GARAGE)
SERVICE FOR LOWE'S GARAGE, DEAD ENDED - 1 FIBRE DUCT - SERVICE TO MURPHY'S STABLE
PURCHASE ST.
Plotted