

APPLICATION/AGREEMENT

For Trench/Disturbance Permit within the City of New Bedford

Permit #

153-18

Dig Safe #

2018-1505838

Date: April 12, 2018

TO THE MAYOR AND CITY COUNCIL:

DISTURBANCE PERMIT/TRENCH SAFETY PERMIT

Permission is hereby requested to excavate the surface of: _____ and/or: _____ Private Property
Provide Sketch

Location of Work: 83 Ruth Street

FOR INSPECTION ONLY A 24 HOUR
NOTICE IS REQUIRED AND THE
CONTRACTOR/APPLICANT IS
REQUIRED TO NOTIFY THE D.P.I.
@ 508 979-1550 Press 4 Repair
PERMIT EXPIRES 1 YEARSubstantially as per plan annexed, for the purpose of: _____
inspection of gas main and services

Work will begin (weather permitting) on: 4-13-18

Work will end (weather permitting) on: 4-13-18

Applicant Name: M. Reid

Excavator (s) Name: ON FILE

Company Name: MSR Utility Management

Hoisting Equipment License Number: _____

Grade: _____ Expiration Date: _____

Contact Number: 978-649-0921

Name & Contact Number of Insurer: Frances Provencher Ins.

978-459-8681

Competent Person on Work Site: M. Reid

APPROVED BY: Stephen Dwyer DATE: 4-12-2018

TITLE: Engineering Supervisor

This permit shall be posted at the work site, and shall remain until the work is completed. It is subject to inspection at all times.

PREMARK FORM

Location #7 83 Ruth St New Bedford, MA

Premark Date 4/9/18

Foreman Name M. Reid

Digsafe # 20181505838 Date: 4/13/18 1PM

Picture # From phone

Circle all that apply

Private Property: Y or ☒ Pavement to be broken: ☒ or N


Sidewalk / ☒ Street / Grass / Driveway


Police Detail Needed: ☒ or N

State Rd: Y or ☒ N

Guaranteed Road: Y or N What Year? _____

Draw Sketch Below





PREMARK FORM

Location #6 Thuman ST New Bedford, MA

Premark Date 4/9/18

Foreman Name M. Rivas

Digsafe # 20181505831 Date: 4/13/2018 1PM

Picture # From phone

Circle all that apply

Private Property: Y or ☒ Pavement to be broken: ☒ or N


Sidewalk ☒ Street / Grass / Driveway


Police Detail Needed: ☒ or N

State Rd: Y or ☒


Guaranteed Road: Y or N What Year? _____

Draw Sketch Below











Request Number: 20181505831 Date 04/10/2018 Time 12:51		
Latitude: Longitude:		
State: MASSACHUSETTS Municipality: NEW BEDFORD		
Address / Intersection: TALLMAN ST		
Nearest Cross Street 1: Nearest Cross Street 2:		
Additional Information: (4) AREAS PREMARKED		
DIGGING 2X2 TEST HOLES TO INSPECT RECENTLY INSTALLED GAS MAIN/SERVICES		
Nature Of Work: INSPECT RECENTLY INSTALLED GAS MAIN/SERVICE		
Area Of Work: WORKING IN THE EXISTING GAS TRENCH		
Area Is Premarked: Y Start Date: 04/13/2018 Start Time: 13:00		
Caller: AMY A Title: CLERK Return Call: ANYTIME		
Phone#: 978-649-0002 Fax#: Alt. Phone#:		
Email Address: MSRUTILITY427@GMAIL.COM		
Contractor: MSR UTILITY MAINTENANCE CORP		
Address: 209 PLEASANT ST City: DUNSTABLE State: MA Zip: 01827		
Excavator Doing Work: MSR UTILITY MAINTENANCE CORP		
Member Utility List		
Code	Abbreviation	Name
AB	AT&T	AT&T TRANSMISSION
CN	NSTREL	EVERSOURCE - ELECTRIC
CP	NSTGAS	NSTAR GAS
E115	ESINET	ESI ADVANCED WIRELESS NETWORKS, LLC
HK	COMCAS	COMCAST - PEMBROKE
WW	VERIZN	VERIZON
ON	ONTARG	ON TARGET LOCATING
RJ	VERIZN	VERIZON

- There may be non-member utilities in the area that you need to notify.
- Electric and other companies may not mark lines they don't own or maintain. You may want to contact them for more information.
- The excavator is responsible to maintain markings placed by member utilities.
- You are required by law to call 911 if pipeline damage results in a gas release.

DIG SAFE ENCOURAGES A COPY OF THIS ELECTRONIC TICKET ON SITE AT ALL TIMES.

[Create New](#)
 [Create From Existing](#)
 [Print Ticket](#)
 [Return To Menu](#)
 [Return To Home](#)