

Work Order Number: 19-013797

9/5/2019
1:39 PM

Category: Highway Priority: _____
 Problem: Pre Inspection Crew: _____
 Cause: _____ Supervisor: MANNY WASHBURN
 Main Task: Investigate Status: New Work Order
 Work Order Start Date/Time: _____ Work Order End Date/Time: _____
 Department: HW Highway Area: _____
 Division: _____ Sub-Area: _____
 Sub-Division: _____

Location (s)

61 TARKILN HILL RD **KIRBY'S FUNERAL**

Comments for Crew

PLEASE TAKE PICS OWNER STATING LARGE HOLES WHERE STREET MEETS DRIVEWAY
 SOUNDS LIKE DRIVEWAY BROW
 ONE ON TARKILN HILL SIDE
 OTHER ON BELLEVILLE RD SIDE DRIVEWAY

Task Start Date/Time: _____ Task End Date/Time: _____

Task Code: HWT620 Task Description: Investigate

Employee Number	Employee Name	Time Type				Units Hours
		Reg	OT	Normal	Type	
11404	PERCY REYNOLDS	0.00	0.00	0.00	REGULAR TIME	35 min

Equipment Code	Equipment Description	Units
63		

Material Code	Material Description	Units

Fluid Code	Fluid Description	Units

ASPHALT 12x26' DW 18' UNCOVER GRANITE CURB
 12x125' SW INTERESTED IN CEMENT
 Belleville DW