

Work Order Number: 19-016309

*Pick*

10/21/2019  
9:30 AM

Category:	Street Maintenance	Priority:	
Problem:	Pre Inspection	Crew:	
Cause:		Supervisor:	DANIEL PERRY
Main Task:	Inspect	Status:	New Work Order
Work Order Start Date/Time:		Work Order End Date/Time:	
Department:	HW Highway	Area:	
Division:	HWY Highway	Sub-Area:	
Sub-Division:			

Location (s)  
1037 VICTORIA ST

Comments for Crew  
click fix #6854788 please check manhole cover

Task Start Date/Time: Task End Date/Time:  
Task Code: CYT300 Task Description: Inspect

Employee Number	Employee Name	Time Type				Units
		Reg	OT	Normal	Type	
12865	MANUEL ROSE	0.00	0.00	0.00	REGULAR TIME	Hours

Equipment Code	Equipment Description	Units

Material Code	Material Description	Units

Fluid Code	Fluid Description	Units

Drain Manhole Casting is sunken at 1059  
see pics