APPLICATION/AGREEMENT

For Trench/Disturbance Permit within the City of New Bedford

Permit # Dig Safe#20223411816

Date: 08/25/2022

Permission is hereby requested to excavate the surface of: X City Property TO THE MAYOR AND CITY COUNCIL: DISTURBANCE PERMIT/TRENCH SAFETY PERMIT and/or X_Private Property

Provide Sketch

Applicant Name: Location of Work: Court St. @ Cottage St. Work will begin (weather permitting) on: Emergency gas line maintenance. Between Cottage St & Cedar St., Steven Botelho (gk) Working in street & street to house and 50 ft in each direction at intersections. August 25, 2022 Excavator(s) Name: AUTHORIZATION FROM THE INFRASTRUCTURE, TRAFFIC MANAGEMENT COMMISSIONOR OF PUBLIC PLANS MAY BE REQUIRED ROADWAY CLOSURES WILL REQUIRE

Contact Number: Company Name: Eversource 339-987-8010 Hoisting Equipment License Number: Name & Contact Number of Insurer: Grade: Expiration Date:

Competent Person on Work Site: ON FILE APPROVED BY: DATE: 9-21-2022

This permit shall be posted at the work site, and shall remain until the work is completed. It is subject to inspection at all times.

Work completed prior to D.P.I. approval under emergency work order for Class II Leak

HIM-JOG

prior to DPI sign off of

Trenches must be maintained weekly until final paving is

> Permit only valid for three months from date of approva

2 Digsafes called: Court @ Cottage Cottage from Cottage to Ash St.

		_					OOM	go i	TOIT (30111	age it	, , 101	100							
		EV	/ER	SŧL	JRCE					DAILY ACTIVITY REPORT										
DigSafe/ CBYD Number					PERMIT#					PROJEC		T#	GAS-EMG		IGGAS2Y		Unique ID :	10231720	10231720-10-[VQ81]	
ADDRESS	95 CO	95 COURT ST			TOWN:		NEW BEDFORD				DATE:		08/25/22		:		WORK ORDER- TASK:		-10	
SHEET 1	EET 1 of					ļ					LEAK CLASS						TYPE OF WORK:	GASMAINTENANCE		
		r:					WAMFWO:		30419200				WAMCTE # 9568		839					
PIPE RETIREMENT																				
FACILTY_TYPE					Die	MATERIAL			3/4				NGTH 24		F	PRESSURE	LÍ	VIN YR 1974		
						Plastic				3/4								Ш	19/4	
PIPE INS	PIPE INSPECTION																			
No	40 YY																			
PIPE INS	STALL																			
FACILITY TYPE	MATERI	AL SI	ZELI	ENGTH	PRESSUR	EMI	ETHOD P				ALLED/ LACED	COV	F AT		NNECTION AT MAIN	IN	EFV STALLED	EFV SUBTYPE	EFV COMMENTS	
Main	Plastic	2"		1'	Ĺ	1	Direct Bury					5,	0"							
Service	Plastic	0.	50"	24`	LI			t 60' or Less I		Main to Valve		2`	0"	Fused			No		Large volume meter per carlos	
			1			土									_					
PRESSUE	RE TEST								-					_		_				
MEDIUM	TYPE	STAR		ART TIN			TART URE(PSIG)		FINISH TIME		FINISH PRESSURE(F					PERFORMED BY		SOAP TESTED	NOTES	
Air	Service be 200 ft	elow	low 2022-08 14:04:0				100				-08-25 :19:00		10		100 15mir		son arruda	Yes	At all connections	
Air	Main		2022-08- 13:00:00				100		2022-0 14:0		08-25 00:00		100		100 60min		son arruda	Yes	At all connections	
RESTORA	ATION							_								_				
CONSTR	LOCATION			XISTING	SH	EXIS						EQUIRED DEPTH		TEMPORARY REPAIR ACTIO			ACTION HOD	% COMPACTED		
Hot Asph	Hot Asphalt		Street		alt			4		0"	5`0"	0"						cted per andards	90	
Concrete		Sidewalk		Concr	ete		4		6,	0"	0" 4'0"		4"					cted per andards	93	
MATERIA	ALS															-				
No				- -								· 								
	TION OF																			
Bar and foot of 2	tested Dug inch plast	g on fi	nighes d a ne	st readir ew tee a	ig found le nd inserte	ak d d 24	on T R I feet of	etired half-i	l 1 foot inch pla	of pla istic t	istic 2 io hrough	nch m old th	ain ar ree q	nd 24 uarte	feet of threer inch plast	e-qu ic fro	iarter inch ; m valve to	olastic Inst main	alled new 1	
PERSON	NEL																			
FOREMA	N / WORK	ING L	EADE	R / INS	PECTOR															
SIGNATU	RE:																			

