

APPLICATION/AGREEMENT

Permit # 509-2009

For Trench/Disturbance Permit within the City of New Bedford

Dig Safe# 20224412828Date: 11/4/2022

TO THE MAYOR AND CITY COUNCIL:

DISTURBANCE PERMIT/TRENCH SAFETY PERMIT

Permission is hereby requested to excavate the surface of: X City Property and/or X Private Property

Provide Sketch

Location of Work: 66 Rockdale Ave.Cove Rd -Emergency Gas Leak RepairWork will begin (weather permitting) on: November 4, 2022Applicant Name: Steven Botelho (ra)

Excavator(s) Name: _____

Company Name: Eversource

Hoisting Equipment License Number: _____

Grade: _____ Expiration Date: _____

Contact Number: 508-441-5817

Name & Contact Number of Insurer: _____

Competent Person on Work Site: ON FILEAPPROVED BY: Stephen Caplan DATE: 12-6-2009TITLE: Asst. City Engineer

This permit shall be posted at the work site, and shall remain until the work is completed. It is subject to inspection at all times.

Trenches must be maintained
weekly until final paving is
completedWork completed prior to D.P.L. approval under
emergency work order for Class II Leak

*no work within City layout.
Rockdale Ave under 5
year maintenance.

ROADWAY CLOSURES WILL REQUIRE
AUTHORIZATION FROM THE
COMMISSIONER OF PUBLIC
INFRASTRUCTURE. TRAFFIC MANAGEMENT
PLANS MAY BE REQUIRED.Permit only valid for three months
from date of approval

DigSafe/
CBVD
Number

PERMIT#

PROJECT#

GAS-EMGAS2Y

Unique ID : 11065607-10-[0151]

ADDRESS:

66 ROCKDALE AVE

TOWN:

NEW BEDFORD

DATE:

11/30/22

WORK
ORDER-

11065607-10

SHEET 1 of

LEAK
REPORT #

CLASS

WAMFWO: 30466511

WORK:

GASMAINTENANCE

Contractor:

PIPE RETIREMENT

No

PIPE INSPECTION

No

PIPE INSTALL

FACILITY
TYPEMATERIAL
SIZELENGTH
PRESSUREMETHOD
OVERALLPIPE
REPLACED/
LENGTHDEPTH
OF
COVERCONNECTION
AT MAINEFV
INSTALLEDEFV
SUBTYPEEFV
COMMENTS

PRESSURE TEST

No

RESTORATION

MATERIALS

No


DESCRIPTION OF WORK COMPLETED

Tighten existing 2" dresser

PERSONNEL

FOREMAN / WORKING LEADER / INSPECTOR

SIGNATURE:



EVERSOURCE		CTE UNIT LINES
No Data Available		
PERMITS		
No Data Available		
OTHER ATTACHMENTS		
No Data Available		
No Data Available		