New Bedford Water Works. No. 1084

RETURN OF SERVICE PIPE.					
Estate No. 100).	6	Oedar	Street	t, for
William 7. Luce 1 (Hant Stable)					
Put in by Gffaw & allen.					
Service Pipe 78 inches diameter. July 127 1872					
service sipe ja inches wameter.					
Cost to be paid by the City.			Cost to be paid by the Proprietor.		
271- 10 1964	5	21	3. 7 lineal fact courts averaged at / Hote		10
2/25 lineal feet earth exc. at/9/cts.	9	06	J. lineal feet earth excavated at / Stets.		68.
lineal feet rock exc. at cts.			lineal feet rock excavated at cts.		
25.8 lineal feet lead pipe at 28 cts.	7	22.	57.2 lineal feet lead pipe at 28 cts.	1	46
	1	20.			1 4
lineal feet iron pipe at cts.			lineal feet iron pipe at cts.		
Lapling Meiner	10	90	Extre	2	00.
1 cl	23	48	1		
Q ELS	2	a			
Bar to the second					
				1,	,,v
		1	Amount charged Proprietor,	7	14.
Amount paid by the city,	21	48	Total Cost,	23	62.0
See of about aft! for I have B Wheeler superintendent.					
Stable. I think one will					
Pla	H	1			

the mosell he wants to kay for this)

SERVICE PIPE, No. 1084

Laid for

Jany Luce

100 Ceclas Street.

1872

Expense to the City,

Expense to the Proprietor,

Total, - - -

Water Registrar's Office,

New Bedford, 6/26, 1872

To the Sup't of the N. B. Water Works:

Please put in a Service at the estate named on the back of this Order and return the expense thereof, &c., to my Office.

Attend and f

Water Registrar.