

6%

SERVICE PIPE RETURN.

No. 15125

For _____ David Stone.

No. N. side Mill, W. of Tremont Street.

27-26

| | | | | |
|---|---|-------|-----------------|------|
| _____ | lineal feet of earth excavated at | _____ | cents per foot, | |
| _____ | lineal feet of rock excavated at | _____ | cents per foot, | |
| 13 | lineal feet of $\frac{5}{8}$ inch ⁴ lead pipe at | 14 | cents per foot, | 1 82 |
| _____ | lineal feet of _____ inch iron pipe at | _____ | cents per foot, | |
| _____ | lineal feet of _____ inch tin lined pipe at | _____ | cents per foot, | |
| _____ | labor | | | 2 39 |
| Proportion of other expenses for putting services into premises | | | | 2 00 |
| Amount \$ | | | | 6 21 |

April 15th, 1913.

R. B. P. Boyges hall Superintendent.

WATER REGISTRAR'S OFFICE.

April 11, 1913 191

Please put in a Service upon the premises described above, and make return of the expense of the same to this office.

C. Baylies Water Registrar.
per H. P.

$$\frac{24}{16}$$

15125

N. S. of Mill, W. of
Fremont
blavid Stone